



**S.R. 376 West Mainline Detour
Section B**

All Trucks Must Exit

1. Exit SR 376 Eastbound to SR 8 / Wilkinsburg (Exit 78B).
2. Follow Ardmore Blvd to Penn Ave.
3. Turn Left onto 5th Ave.
4. Follow 5th Ave to SR 376 W on Ramp.

**5. For Detour Access from Braddock Ave.
Follow Braddock Ave to Penn Ave Make Left onto Penn Ave.**

▨ Construction Area
 Truck Route
 Detour Route
 Vehicle Detour